

5/42

SPLIT

DART AEROSPACE LTD		Work Order:	24342 B
Description: Spring		Part Number:	D3141-1
Drawing: D3141 Rev.A		Qty:	10 5

Step	Location	Procedure	By	Date	Qty
1	EXPEDITING	Open W/O	HJ	05.09.26	10
2	PURCHASING	Issue P/O: <u>2008727</u> Make as per dwg D3141 Possible Supplier: Avialta (replaces Bell p/n 204-032-734-001) Material release note required	U	05.09.26	10
3	RECEIVING	Receive and inspect for transit damage Ensure material release note is attached	DL	05/10/03	5
4	QC	Inspect Level 6 Check dims to dwg	CY	05/09/09	3
5	STORES	Identify and stock	U	05.10.20	5
6	EXPEDITING	Close W/O Inspect level 21 Cost / part <u>21.40</u> <u>545</u> <u>05/10/24</u> <u>(5)</u> <u>19.91</u>	CY	05/10/21	5
			CS	05/10/24	5

Rev	Date	Change	Revised By	Approved
A	02.06.12	New Issue	NG	02.06.12

RELEASED

02/06/12

2296
Friedrich


✓



DESIGN #	DRAWN BY UP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3141	REV. A SHEET 1 OF 1
DATE 02.05.01		TITLE SPRING	SCALE 2:1
A	02.05.01	NEW ISSUE	

SPECIFICATION CONTROL DRAWING

RELEASED
02.05.01



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 24342

D3141-1 SPRING

- 1) POSSIBLE SUPPLIER: BELL P/N 204-032-734-001
- 2) MATERIAL: SPRING STEEL, $\phi 0.035$ WIRE
- 3) FINISH: CAD PLATE PER QQ-P-416F CLASS 1 TYPE II
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Eagle Copters Maintenance Ltd

823 McTavish Road, NE Calgary, Alberta T2E 2G9

TCCA AMO Approval No. 6-81

LOT #: LT-05-018151



Sold To: SO05-02589.001

Sold Date: 9/30/2005 9:40:59PM

Part No: 204-032-734-001

Description: SPRING

Serial No:

Condition: New

Qty Sold: 5.00

Cure Date:

Manufacturer: Bell Helicopter (Manufacturer)

	Cycles	Hours
Total Time:		0.0

TSO:

Details of work performed/reason for removal

Additional work to be performed upon installation

The maintenance described has been performed in accordance
with the applicable standards of airworthiness

September 30, 2005

Inspector

Lic. No./Stamp



Maintenance Release